

48K Spectrum RAM Diagnosis

Test 1

POKE 50000,85
and then
PRINT PEEK 50000



85 = 01010101

Test 2


POKE 50000,170
and then
PRINT PEEK 50000

170 = 10101010

Look for incorrect bit/s in pattern to identify faulty IC/s



Lower RAM



Upper RAM